

# Oil Field Environmental Incident Summary

**Incident:** 20150421135639      **Date/Time of Notice:** 04/21/2015 13:56

**Responsible Party:** PETRO-HUNT, L.L.C.

**Well Operator:** PETRO-HUNT, L.L.C.

**Well Name:** USA 2D-3-1H

**Field Name:** CHARLSON

**Well File #:** 16059

**Date Incident:** 4/21/2015      **Time Incident:** 06:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 153

**Rng:** 95

**Sec:** 2

**Qtr:**

**Location Description:**

**Submitted By:** Derek Enderud

**Received By:**

**Contact Person:** Derek Enderud  
PO BOX 935  
BISMARCK, ND 58502

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Treater Popoff

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units
Oil	1	Barrels

Recovered	Units
-----------	-------

Followup	Units
1	barrels

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 4/27/2015

**Clean Up Concluded:** 4/23/2015

**Risk Evaluation:**

None

**Areal Extent:**

Most stayed on location, some misted off.

**Potential Environmental Impacts:**

Mist that left location is on vegetation.

**Action Taken or Planned:**

Waiting for USFS to visit site to make a determination on what they recommend for cleanup.

**Wastes Disposal Location:****Agencies Involved:****Updates**

---

**Date:** 4/21/2015    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:****Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

According to the incident summary, this spill impacted areas off of location. Followup is necessary to ensure proper cleanup.

---

**Date:** 5/12/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:****Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

I arrived at the site at 14:36 p.m. The weather was cloudy, 59°F, with the wind from the southeast at 10-20 mph. The treater and tank system are located south of the well on an old well pad in the next section (Section 11). This pad has four treaters and numerous tanks, along with an older active well. There is a flare located on the south side of the pad. On the other side of the pad are trees and vegetation that were sprayed with oil. This pad is located on U.S. Forest Service pasture land. The U.S. Forest Service has jurisdiction on this cleanup. No further followup needed at this time.  
48.08587; -102.86850